PART NAME	PART #	QTY	REASON
PILOT TUBES	A1891	4	AD NOTE: 95-01-02
			HC-SB-61-374R1

H54818
H42474
H42465
H42436
NOTE: 1490.3 TTSN

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022
205-426-7022
REPAIR STATION #S6PR302X

MAJOR OVERHAUL. BLADES REFINISHED. PARTS DYE PENETRANT INSPECTED, MAGNAFLUXED, REPLATED & REPLACED WHERE REQUIRED. DEICER BOOTS INSTALLED. PROPELLER TRACKED, BALANCED, SET ANGLES, GREASED AND PAINTED. COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM.
BLADE S/N#'S INSTALLED ARE: H54818, H42474, H42465, H42436

WORK ORDER # SR- 14290
MODEL # HC-B4TN-5GL
BLADE MODEL # LT10282NS-5.3R
HUB SN # CDA3137M5
DATE: 06/30/2021

JAMES M GAITHER,
GENERAL MANAGER